



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: **04/24/2014**

Reviewed *PBS*

Mine Name: Champlin #1	Permit Number: S/023/0104	Mine Status: Active
Operator Name: Nephi Sandstone Corporation	Inspection Date: 04/09/2014	Permit Fees: Delinquent
Inspector(s): Wayne Western	Inspection Time: 9:00 - 9:30 AM	Bond Amount: \$19,700
Attendee(s): Jerry Manfield	Weather: cool clear skies	Bond Escalation: 02/10/2014
Inspection Purpose: Routine inspection		Prior Inspection: 10/17/2013

Conclusions and Recommendations

There was an excavator on site. The Division has told the Operator that they are suspended from mining at the site until permit fees are paid. The bond is due for escalation and the Operator has until June 2, 2014 to post additional bond. BLM should be notified about activities on the site.

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds Mining appears to have taken place even though the NOI was suspended due to lack of permit payments.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls) There are near vertical highwalls at the site. There are no warning signs or fences.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages/Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: _____

CC: Duane Bays

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/- Inspection Summary/Inspection Forms/Inspection form 3.0.1.pdf



Photo taken April 9, 2014 note large stockpile of material and location of cell phone tower, compare to photo taken August 14, 2013.



Photo taken August 14, 2013 no large stockpile of material note location of cell phone tower, compare to photo taken April 9, 2014.



Photo taken April 9, 2014, note that the slope of toe of the hill with the cell phone tower is different than the one taken on August 14, 2013. Also the shape of the piles behind the slope



Slope of toe is different in this picture taken April 9, 2014.